

Trunk Shaker Barrel Clamp

Part Number: 601334



This new Trunk Shaker Barrel Clamp Update Kit was designed to eliminate the barrel roll issue where the grease zerks move and are difficult to access and improves the serviceability of the trunk shaker head.

The new design comes standard on all 2018 Oxbo 6230 Harvesters and can be added to the 2017 and older Oxbo 6220 Harvesters.



The clamp is not standard parts in a trunk shaker minor or major rebuild kit, but can be added to a rebuild by ordering the part number above.

Contact your dealer or call 360-354-1500 ext. 3 for more information
www.oxbocorp.com

WN-0107